




STEPS TO CREATING A COPPERFLEX[®] DIE

KEY BENEFITS TO A COPPERFLEX[®] DIE:

- Can be repeatedly mounted and dismounted for repeat jobs
- Highly flexible, conforms well when wrapped around a cylinder
- Can be used for a Unifraxion[®] or texture application
- One plate will perform multiple, consistent quality job re-runs

The Steps to Creating a CopperFlex® Die



STEP

1

ORIGINAL ART

UEI® Group loves working with a creative customer who seeks to capture attention. We want your product to be flawless but in order for us to make that happen, we need the art to be in vector format and that it follows our Digital File Preparation Tutorial.



STEP

2

DIGITAL FILE TUTORIAL


UEI® Group has developed an easy-to-follow Digital File Preparation Tutorial. The tutorial walks you through the basic digital artwork requirements for manufacturing your engraved die.

* Add all necessary information for manufacturing the order, including any art instructions.

ORIGINAL FILE ART



ART NEEDED BY UEI® GROUP
IN OUTLINE MODE



STEP

4

FINISHED PRODUCT

We did it! We created a masterpiece and now it's time to ship the product. You will receive an email or fax from us, stating your order has been shipped along with the tracking information.

